



# Equipment Inspection

LANYARD- DAMAGE PHOTOS





Fraying






Cut and Fraying

Fraying due  
to an added  
point of  
friction





Welding  
Splatter